




435 - 1: cervena RhB - stopa 01.bmp




435 - 2: cervena RhB - stopa 02.bmp




435 - 3: cervena RhB - stopa 03.bmp




435 - 1: cervena RhB - stopa 04.bmp




435 - 1,2,3: cervena RhB 05.bmp




435 - 1,2,3: cervena RhB 06.bmp




435 - 1,2,3: cervena RhB 07.bmp




435 - 1,2,3: cervena RhB-teflon 08.bmp





435 - 4: cervena RhB-stopa 09.bmp




435 - 4: cervena RhB-stopa vnitrek 10.bmp




435 - 4: cervena RhB-stopa obvod 12.bmp




435 - 4: cervena RbB - poskozeni okolo stopy 13.bmp




435 - 4: cervena RhB - poskozeni okolo stopy 14.bmp




435 - 4: cervena RhB - poskozeni okolo stopy 15.bmp




435 - 4: cervena RhB - poskozeni okolo stopy 16.bmp




435 - 4: cervena RhB 17.bmp




435 - 4: cervena RhB 18.bmp



435 - 4: povrch substratu - kontrola 19.bmp



435 - 4: povrch substratu - kontrola 20.bmp



435 - 4: povrch substratu - kontrola 21.bmp

